

Member Present in Meeting :

- 1) SEE O&M Circle GESCOM Bidar.
- 2) EE O&M Division, GESCOM, Bidar.
- 3) DCA O&M Circle GESCOM, Bidar.
- 4) AEE O&M Sub-division GESCOM, Bidar
- 5) AEE O&M Sub-division GESCOM, Kamthana
- 6) AE (T) O&M Circle GESCOM Bidar.
- 7) AE (T) O&M Sub-division GESCOM Bidar.
- 8) AAO. I/c. I/A O&M Division, GESCOM, Bidar.
- 9) AAO. O&M Division, GESCOM, Bidar.
- 10) Sr. Assistant O&M Division, GESCOM, Bidar.
- 11) JE O&M Circle GESCOM Bidar.
- 12) HT-70 KMF Nandini Dairy
- 13) HT-115 Vishal Megha Mart
- 14) HTBP-13 Sharada Stone Crusher, Hupla
- 15) HTBP-24 Sri. Swami Samarth Engineer Ltd., NH-50 load project (Crusher limit).

GULBARGA ELECTRICITY SUPPLY COMPANY LIMITED

Phone No : 08482 227892

Fax No. : 08482 222092

CIN : U4010KA2002SGC030436

E-mail : seonmbdr@gmail.com

Website : gescom.in



Superintending Engineer Ele.,
O&M Circle, GESCOM, Bidar
KEB Road, Bidar-585401.

No. BDR/SEE/EE(O)/AEE(O)/AE(T)/F-134 /2022-23/ 396-102 Date: 28-04-22

Proceedings of EHT/HT consumers interaction meeting held on 27-04-2022 under the Chairmanship of the SEE O&M Circle GESCOM, Bidar.

At the outset SEE O&M Circle, GESCOM Bidar welcomed all the EHT/HT consumer and officers present in the meeting.

The SEE O&M Circle, Bidar reviewed regarding complaints received during last EHT/HT consumer meeting conducted on 19-01-2022 and its compliance.

1) HT-70 :- KMF Nandini Dairy :-

The representative expressed that, the electricity bill payment is being unable to be paid though check. The AAO Bidar Sub-division has clarified that, due to over writing of date in the check, the check was bounced / dishonoured.

The SEE clarified, the said problem with TRM over phone and assured the representative of the KMF that, the problem will be solved by this month, and directed EE Bidar to write an application to the TRM, if the problem is not resolved.

2) HT-115 :- Vishal Megha Mart :-

The consumer expressed, the satisfaction towards the un-interrupted power supply. SEE expressed, its our pleasure and to inform if there is any problem in the power supply problem.

3) HTBP-13 :- Sharada Stone Crusher, Hupla :-

The consumer expressed, regarding the power supply interruptions to their installations, due to which there is production loss.

The SEE explained that, 50% of the load shifted to 33/11kV Joldabka Sub-station due to which the interruptions were reduced to minimum and assured that, the further interruptions will be reduced soon.



..2.


4) HTBP-24 Sri. Swami Samarth Engineer Ltd., NH-50 load project
(Crusher limit)

The consumer expressed that, daily there is power supply interruption.

The SEE explained that, due to line fault, there were interruptions and assured to the consumer that, it will be reduced from now onwards.

Finally, meeting concluded with vote of thanks by the chair.




27/4/21
Superintending Engineer (Ele),
O&M Circle, GESCOM, Bidar.

Copy Submitted for kind information to:-

- 1) The Chief Engineer (Electy), (Operations), Corporate Office GESCOM, Station Road, Kalaburagi.
- 2) The Chief Engineer (Electy), O&M Zone, GESCOM, Vidyut Bhavan, Atal Bihari Vajipay Layout, Near Kendriya Vidyalaya School, Kotnoor (D), Kalaburagi-585102.

Copy to :-

- 1) The Executive Engineer (Ele), O&M Division GESCOM, Bidar/ Humnabad.
- 2) The Asst. Executive Engineer (Ele), O&M Sub-division, GESCOM, Bidar / Kamthana/ Bhalki for information and needful action.

MF/OC.