

GULBARGA ELECTRICITY SUPPLY COMPANY LIMITED

Phone No : 08482 227892

Fax No. : 08482 222092

CIN : U4010KA2002SGC030436

E-mail : seonmbdr@gmail.com

Website : gescom.in



Superintending Engineer Ele.,
O&M Circle, GESCOM, Bidar
KEB Road, Bidar-585401.

No. BDR/SEE/EE(O)/AEE(O)/AE(T)/F-134 /2021-22/*Cys-24*

Date: *28-12-2021*

Proceedings of EHT/HT consumers interaction meeting held On 28-12-2021 under the Chairmanship of the Superintending Engineer (Ele), O&M Circle, GESCOM, Bidar.

At the outset SEE O&M Circle GESCOM, Bidar welcomed EHT/HT consumers & all the officers present in the meeting.

The Superintending Engineer (Ele), O&M Circle, GESCOM Bidar enquired about the various problems faced by EHT/HT consumer and guided the concerned officers as well as consumers accordingly.

1) MEKHT-01 : M/s SSV Growell Hatcheries India (P) Ltd Nirna :-

The representative of M/s SSV Growell Hatcheries India (P) Ltd Nirna, complained that the HT line feeding to their farm (line executed under self execution) is being tapped / hooked by the villagers.

The Executive Engineer (Ele), O&M Bidar assured of shifting the village load to NJY feeder.

2) KHT-06 : M/s Karanja Industries Pvt Ltd (Rubber Division) :-

The representative of M/s Karanja Industries Pvt Ltd, (Rubber Division), Plot No.01, KIADB IA Kolhar (K) requested, to remove the audit short claim amount of Rs.10,58,152/-. In turn AO (I/A) explained in detailed about the matter and SEE directed the concerned EE & AEE Kamthana Sub-division to verify the case and report to this office within a week's time.

Later, during the discussion EE O&M Bidar expressed that, even after shifting the load, still the interruptions are occurring and intern EE C&M advised to convert 11kV class of voltage to 33kV voltage class in order to avoid the interruptions. The representative of the firm agreed and responded positively to take up the matter with the higher-up's of the firm.

3) HT-70 :- KMF Nandini Dairy at Chickpet, Bidar.-

The representative of M/s KMF Nandini Dairy complained that, the check is dishonoured, as there is a minor correction in the date of issue of the check.

DCA Bidar directed AO Bidar to look into the matter and resolve it, as early as possible.

Finally, meeting concluded with vote of thanks by the chair.


28/12/24
Superintending Engineer (Ele),
O&M Circle, GESCOM, Bidar.

Copy Submitted for kind information to:-

- 1) The Chief Engineer (Electy), (Operations), Corporate Office GESCOM, Station Road, Kalaburagi.
- 2) The Chief Engineer (Electy), O&M Zone, GESCOM, Vidyut Bhavan. Atal Bihari Vajipay Layout. Near Kendriya Vidyalaya School, Kotnoor (D), Kalaburagi-585102.

Copy to :-

- 1) The Executive Engineer (Ele), O&M Division GESCOM, Bidar/ Humnabad.
- 2) The Asst. Executive Engineer (Ele), O&M Sub-division, GESCOM, Bidar / Kamthana/ Humnabad/ MannaEkHELLi for information and needful action.

MF/OC.

Member Present in Meeting :

- 1) SEE O&M Circle GESCOM Bidar.
- 2) EE O&M Circle GESCOM Bidar.
- 3) EE O&M Division, GESCOM, Bidar.
- 4) EE C&M Division, GESCOM, Bidar.
- 5) DCA O&M Circle GESCOM, Bidar.
- 6) AEE 110kV Nodal officer Chidri.
- 7) AEE O&M Sub-division, GESCOM, Humnabad
- 8) AEE O&M Sub-division GESCOM, Kamthana
- 9) AEE Vigilance Bidar.
- 10) A.O. I/A O&M Division, GESCOM, Bidar.
- 11) A.O. O&M Division, GESCOM, Humnabad.
- 12) AE O&M Circle GESCOM Bidar.
- 13) AE 110kV Kolhar.
- 14) S.O. Andoor
- 15) Sr. Assistant I/A O&M Division, GESCOM, Bidar.
- 16) Sr. Assistant O&M Sub-division, GESCOM, Bidar.
- 17) JE O&M Circle GESCOM Bidar.
- 18) JE O&M Circle GESCOM Bidar.
- 19) MEKHT-01 : M/s SSV Growell Hatcheries India (P) Ltd Nirna.
- 20) KHT-06 : M/s Karanja Industries Pvt Ltd
- 21) HT-70 :- KMF Nandini Dairy Chikpet, Bidar.
